

Health & Safety Guidelines

NO PPE, NO WORK



The Organizers are required to clearly inform all the contractors that NO work will be allowed without adequate PPE for the job / task. This includes Halls and Loading Bays.

Minimum requirement includes (Steel Toe Safety Shoes, Gloves, High Vis jackets and Hard hat). However the requirement varies as per the task.

PPE can be purchased in ADNEC from the Grocery in the grandstand opposite of the Innovation Lab.




WORKING AT HEIGHT


Work at height (Ladders, scaffolds) must be in maintained and assembled in good condition. An unsafe equipment will not be allowed and will be removed from site.



CORRECT WIRING




Electrical works, wirings and connections must be as per ADNEC Rules and Regulations. Any Unsafe electrical works will be removed and the contractor issued non-compliance warnings.



VALID LICENCES

Forklift / MEWP (Cherry pickers and Scissor Lift) Operators must have VALID LICENSE and training certificate to operate (IPAF etc.) Anyone found operating them without license will be held and referred to authorities.



NO MANUAL SANDING OR GRINDING



Dusting / Sanding / Grinding work to be carried out in the designated areas and outside. Only essential and final touch-ups will be allowed inside. All such machinery must be equipped with built-in suction to extract dust immediately.



SUPERVISED VEHICLE MOVEMENT

Vehicle drivers must not exceed the venue speed limit or in any case to exceed 10 kph in external areas or 5 kph in the halls whichever is lower. Vehicles with the halls should not leave engines running.



All vehicle movement should be supervised.

NO BLOCKAGES



Emergency Exits, Gangways and Fire hose cabinets must NOT be BLOCKED and be kept clear and available at all times.



HOT WORK PERMIT

Any hot work on site requires a HOT work permit issued from ADNEC Facilities Management and ADNEC Health and Safety.



NO SMOKING IN THE VENUE